Navajo Abandoned Uranium Mine

Site Screen Report

This form is for use at the site of abandoned uranium mines (AUM) located on Navajo Nation lands. Applicable sites include all mine and mine features that have or have not undergone reclamation by the Navajo Abandoned Mine Lands Reclamation Program, including features, adits, pits and waste piles. Applicable sites also include all AUM sites listed in the USEPA CERCLIS database, all sites listed in the 2008 AUM GIS Report issued by USACOE and USEPA, all AUM sites on allotment lands associated with the Navajo Nation, and any and all AUM sites not listed in any database located on Navajo lands. Reconnaissance of any sites located on lands adjacent to Navajo lands that may be impacting Navajo lands will need to be coordinated with the authorities appropriate to those lands.

The purpose of the form is to ascertain the status and location of the identified AUM site, and record all immediate site information associated with the mine site. Decisions and recommendations on what additional steps are needed will be provided on a separate document.

Ramco No. 21 AUM Site

Navajo AUM Western Region

Prepared by:

Weston Solutions, Inc.

Contract: W91238-06-F-0083

12767.063.599.1111

January 2011

Part I **Site Identification, Location and Status** Site Names and ID numbers as applicable Mine ID: 90 Map ID: W93 **CERCLIS:** NNN000909063 Navajo Abandoned Mine Land Reclamation Program: NA-0172A; NA-0172B Local name / Aliases: RAMCO No. 21; RAMCO #21 **Chapter and local area:** Coalmine Mesa Chapter County: Coconino State: Arizona **Lat/Long:** 35.7403672327 N / -111.301657341 W **Nearby road and highway:** Indian Route 6730 **Local Post Office:** Cameron, AZ Surface Land Status: check one or more and provide ownership and contact information below **Tribal Trust Land Public lands Tribal Fee Land Private Bureau of Land Mgmt Allotment** State Fee land **Subsurface Mineral Rights:** No information on subsurface mineral rights ownership was found in the EPA/AUM Database.

The mine site surface land status is classified as Tribal Trust Land. Historical documents showed the operator of the mine as the Rare Metals Corporation from 1956 to 1959. No additional ownership / lease information was identified in the EPA/AUM database.

Number of residential structures within 200 feet of mine: None

Estimated volume of mine waste onsite: None

Claim and operator information:

Part II Summary of radiological readings

Highest gamma radiation measurement:

74,778 counts per minute (cpm)

Describe any other radiological measurements:


A total of 4,312 gamma radiation measurements were collected from the mine site, ranging from 9,037 cpm to 74,778 cpm. The measurements are represented in Figures 1 and 2.

Background Readings: 10,524 cpm; 13,166 cpm

Background Average: 11,102 cpm

Distribution Chart and Statistics:

The following chart and statistics were generated by ESRI ArcGIS 9.3.1, and show the general distribution of the site gamma radiation measurements. The horizontal X axis represents the gamma radiation reading levels in cpm (lowest levels to the left). The vertical Y axis represents the frequency of each gamma radiation level.



 Count:
 4312

 Minimum:
 9037,00000

 Maximum:
 74778,00000

 Sum:
 66526897,00000

 Mean:
 15428,31563

 Median:
 14458,50000

 Standard Deviation:
 5844,64472

Part III Status of Reclamation and Mine Waste

The following information was obtained from the Navajo Abandoned Mine Land Reclamation Program (NAMLRP) Point Features Database:

NAMLRP Status of the mine site: Reclaimed: Yes Waste Pile onsite: No

NAMLRP Project Number: NA-0172A; NA-0172B

NAMLRP Mine features: 2 Rim Strip / Pits

The following information was obtained from field observations collected during the 2010 site screening:

Provide description and status of all mine sites and features at site. Include all waste piles, adits, pits and other features, and indicate whether they are open, closed, covered, capped, buried or unreclaimed. Indicate approximate size, shape and extent, including description of any reclamation caps. Note condition of all caps.

of any reciamation caps. Note condition of an caps.
Observed reclamation work and status:
Adits None
Waste Piles None
Pits None

Other Debris and Mine Features

None

Shafts None

Part IV

Site observations and Environs

Observed Structures: list number of and describe human habitation status of structures at the following distances from mine:

0 to 200 feet: None

200 feet to 0.25 mile: None

Observed Public or commercial structure: list and describe all schools, clinics, Chapter Houses, places of business and any other structure used by members of the community at the following distances:

0 to 200 feet: None

200 feet to 0.25 mile: None

Levels measured around the perimeter(s) of the identified structure(s):

None

Observed water sources: list the number and type of wells and surface water sources that are potentially used for human consumption at the following distances from the mine:

0 to 0.25 miles: None

0.25 miles to 4 miles: Little Colorado River Basin approximately 1 mi W of the site

Sensitive environments: note and describe all sensitive environments located within visible range of the mine site, including: wetlands, endangered species, habitats and approximate locations of sites that may be under protection of the government of the Navajo Nation.

None observed

Known Site History: include information from interviews with Chapter officials and residents. Note information on mine ownership, type of mining operation, period of operation, known amount of production, and any other information as provided.

Ramco No. 21 mine consists of an area of 171,346.91 m². The mine was identified as being operational from 1956 to 1959. Historical documents showed the operator of the mine as the Rare Metals Corporation from 1956 to 1959. While operational, the mine had a total reported production volume of 5,471 tons. No other historical information or any additional ownership / lease information was identified in the EPA/AUM database.

Part V Response Action Summary

Summary of Evaluation Factors:

Accessibility:

Was the mine easily accessible to potential human activity? Yes

Radiological Measurements:

Were any gamma radiation measurements collected at the mine greater than two times the site-specific background levels?

Yes

Waste Piles:

Were any unreclaimed waste piles observed at the mine with gamma radiation measurements greater than two times the site-specific background levels? No

Structures:

Were any structures observed within 200 feet of the mine?

No

Potential Drinking Water Sources:

Were any potential drinking water sources observed within 4 miles of the mine? Yes

Reclamation:

Was the mine reported to be previously reclaimed, or did the mine appear to be reclaimed?

Yes

Part VI Photos



Photo 1. Ramco No. 21 mine site



Photo 2. Ramco No. 21 mine site



Photo 3. Ramco No. 21 mine site



Photo 4. Ramco No. 21 mine site drainage

Part VII Contacts Reports and Information

Name: <u>Stanley Edison (928) 871-6861</u>

Eugene Esplain (928) 871-7331

Title or official role (if any): Navajo EPA Superfund Program

Address: PO Box 2946, Window Rock, AZ 86515

Information provided: <u>Lead Regulatory Agency</u>

Name:	
Title or official role (if any):	
Address:	
Telephone number:	-
Information provided:	-
Name:	
Title or official role (if any):	_
Telephone number:	-
Information provided:	
	-
Name:	_
Title or official role (if any):	_
Telephone number:	-
Information provided:	-

Figure 1 - Gamma Radiation Measurements, Above Two Times Background
Ramco No. 21 (90)
Coalmine Mesa Chapter, Navajo Nation






Figure 2 - Gamma Radiation Measurements Ramco No. 21 (90) Coalmine Mesa Chapter, Navajo Nation



Legend

Gamma Radiation Measurements

- 0 10,000
- 10,000 15,000
- 15,000 20,000
- **2**0,000 50,000
- 50,000 100,000
- > 100,000



Mine Site Boundary

Gamma survey conducted 11/2010 Measured as counts per minute (cpm)

Average background 11,280 cpm

